



Hyde-St. John House  
Hartford, CT  
Liszka Travel Agency photo  
Spring, 1976

Negative at Liszka Travel Agency

Front view of the house before the porch was renovated

Hartford County  
APR 26 1977

Photo A # 1 of 4

OCT 6 1977

**PROPERTY OF THE NATIONAL REGISTER**



25

Hyde-St. John House

Hartford, CT

Liszka Travel Agency photo

11/76

Negative at Liszka Travel Agency

Front doorway

Hartford

County

OCT 6 1977

APR 26 1977

Photo B # 2 of 4

**PROPERTY OF THE NATIONAL REGISTER**



Hyde-St. John House

Hartford, CT

Liszka Travel Agency photo  
12/76

Negative at Liszka Travel Agency

Entablature, lunette window and spandrels of doorway

Hartford

OCT 6 1977

County

APR 26 1977

Photo C # 3 of 4

**PROPERTY OF THE NATIONAL REGISTER**



Hyde-St. John House

Hartford, CT

Liszka Travel Agency photo

12/76

Negative at Liszka Travel Agency

Fireplace in southwest bedroom, second floor showing  
high relief wooden carving

Hartford  
County

OCT 6 1977

APR 26 1977

Photo D #4 of 4

**PROPERTY OF THE NATIONAL REGISTER**